



## SOLICITATION ADDENDUM

Date: **10/25/2023**  
Subject: **Waste Tire Processing**  
Solicitation Number: **6100059593**  
Due Date/Time: **10/27/2023 12:00:00 ET**  
Addendum Number: **01**

---

To All Suppliers:

The Commonwealth of Pennsylvania defines a solicitation “Addendum” as an addition to or amendment of the original terms, conditions, specifications, or instructions of a procurement solicitation (e.g., Invitation for Bids or Request for Proposals).

*List any and all changes:*

This addendum is for extension of the referenced solicitation, inclusion of waste tire site photographs, and provide responses to questions that were received. The due date/time is being extended from 10/27/2023 12:00:00 ET to 11/10/2023 12:00:00 ET. Photographs of waste tires are being included in this addendum for additional reference.

Type of Solicitation: Electronic Bid (SRM) - Review the Questions section of your solicitation response to ensure you have responded, as required, to any questions relevant to solicitation addenda issued subsequent to the initial advertisement of the solicitation opportunity.

Except as clarified and amended by this Addendum, the terms, conditions, specifications, and instructions of the solicitation and any previous solicitation addenda, remain as originally written.

Respectfully,

Name: Brady Fries  
Title: Procurement Specialist  
Phone: 717-783-8381  
Email: bfries@pa.gov

Q: Are site visits allowed?

A: Yes.

Q: Do you have any photos of the tire pile site?

A: Yes, please see the most recent site inspection report included in this addendum.

Q: What is required with the remediation plan?

A: There are no remediation plans needed for the cleanup of this waste tire pile. The winning bid is required to follow their approved Cleanup Plan. This plan includes restoring any areas that may have experienced any earth disturbance. This includes putting the area back to approximate original contours as well as seeded and mulching all disturbed areas.

## General Inspection Report

<b>Permit Number</b>	----	<b>EPA ID Number</b>	----
<b>Facility Name</b>	HEBERLING WASTE TIRE PILE	<b>Operator Name</b>	----
<b>Address</b>	18270 ROUTE 954 HWY N	<b>Address</b>	----
<b>City/State/Zip</b>	HOME PA 15747-5902	<b>City/State/Zip</b>	----
<b>Municipality</b>	----	<b>County</b>	----
<b>Responsible Official</b>	Edward Heberling Estate	<b>Title</b>	Responsible Official
<b>Person Interviewed</b>	Lori Heberling	<b>Title</b>	
<b>Lead Inspector</b>	MATTHEW WAYLAND	<b>Telephone #</b>	1
<b>Site ID</b>	836270	<b>Title</b>	SLD WSTE SPCST
<b>PF ID</b>	----	<b>Client ID</b>	----
<b>Inspection Start Date</b>	10/05/2022 10:11 AM	<b>SF ID</b>	----
<b>Inspection Type</b>	FUI - Follow-up Inspection	<b>Inspection End Date</b>	10/05/2022 01:03 PM
<b>Permit Expiration Date</b>	----	<b>Inspection Result</b>	Outstanding Violations - No Viols Req'd
		<b>Days/Week Operated</b>	----
		<b>Max. Daily Volume</b>	----

## Comments

On site October 5, 2022 at approximately 10:00 for a follow up inspection. Reason for the site visit was to view waste tire piles to verify that no cleanup has been conducted and to obtain updated pictures. Upon arriving I made contact with Lori Heberling at the residence located on the property. I explained that a follow up site visit was being conducted to obtain updated pictures. A walking tour was conducted along approximately 100 yards of the east side of Route 954. Pictures of the waste tires were taken.

Additionally, the western side of Route 954 contains an additional tire pile located just into a wooded area along a field. This tire pile was viewed and updated pictures were taken.

If you have any questions regarding this inspection report you may contact me at 814.853.5828 or via email at [mawayland@pa.gov](mailto:mawayland@pa.gov)

## INSPECTION IMAGES



#:

Tires located adjacent to a field on the western side of route 954. Tires cannot be seen from Route 954



#:

Tires located adjacent to a field on the western side of route 954. Tires cannot be seen from Route 954



#:

Tires located adjacent to a field on the western side of route 954. Tires cannot be seen from Route 954



#:

Tires located adjacent to a field on the western side of route 954. Tires cannot be seen from Route 954



#:

Tire pile located along Route 954.



#:

Tire pile located along Route 954.



#:

Tire pile located along Route 954.



#:

Tire pile located along Route 954.



#:

Tire pile located along Route 954.



#:

Tire pile located along Route 954.





#:

Tire pile located along Route 954.



#:

Tire pile located along Route 954.




**#:**  
Approximate location of the tire pile that cannot be viewed  
from Route 954

### Inspection Report Signature Page

This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either Violations noted herein, or other violations identified as a result of review of laboratory analyses. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein. Signature by the persons interviewed does not necessarily imply concurrence with the findings of this report, but does acknowledge that the person was shown the report or that a copy was left with the person.

### Signatures

Person Interviewed	Unable To Obtain Reason: Report Generated Off Site	Date	--/------
Inspector		Date	10/05/2022